

**AmeriSci New York**

117 EAST 30TH STREET

NEW YORK, NY 10016

TEL: (212) 679-8600 • FAX: (212) 679-9392

October 7, 2014

Eisenbach & Ruhnke Engineering, P.C.
Attn: Jack Eisenbach
291 Genesee Street
Utica, NY 13501



RE: Eisenbach & Ruhnke Engineering, P.C.
Job Number 214101690
P.O. #14215
14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire, 2214 Whitesboro St., Utica

Dear Jack Eisenbach:

Enclosed are the results of Asbestos Analysis - Bulk Protocol of the following Eisenbach & Ruhnke Engineering, P.C. samples, received at AmeriSci on Saturday, October 04, 2014, for a 3 day turnaround:

01, 02, 03, 04, 05, 06, 07, 08, 09, 10, 11, 12, 13, 14, 17, 19, 20, 21, 22, 23, 25, 26, 29, 32, 33, 34, 37, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55

The 42 samples, placed in Zip Lock Bag, were shipped to AmeriSci via Federal Express. Eisenbach & Ruhnke Engineering, P.C. requested ELAP PLM/TEM analysis of these samples.

The results of the analyses which were performed following ELAP Protocols 198.1 PLM Friable and/or 198.6 for PLM NOB. ELAP Protocol 198.4 TEM NOB guidelines are presented within the Summary Table of this report. The presence of matrix reduction data in the Summary Table normally indicates an NOB sample. For NOB samples the individual matrix reduction, combined PLM and TEM analysis results are listed in the Summary Bulk Asbestos Analysis Results in Table I. Complete PLM results for individual samples are presented in the PLM Bulk Asbestos Report. Samples near 1% asbestos may be analyzed by EPA 400 pt ct method EPA 600/M4-82-020. This combined report relates ONLY to sample analysis expressed as percent composition by weight and percent asbestos. This report must not be used to claim product endorsement or approval by these laboratories, NVLAP, ELAP or any other associated agency. This report must not be reproduced, except in full without the written approval of the laboratory. This report may contain specific data not covered by NVLAP or ELAP accreditations respectively, if so identified in relevant footnotes.

AmeriSci appreciates this opportunity to serve your organization. Please contact us for any further assistance or with any questions.

Sincerely,

Paul J. Mucha
Laboratory Director

**AmeriSci New York**

117 EAST 30TH ST.
NEW YORK, NY 10016
TEL: (212) 679-8600 • FAX: (212) 679-3114

PLM Bulk Asbestos Report

Eisenbach & Ruhnke Engineering, P.C.
Attn: Jack Eisenbach
291 Genesee Street

Utica, NY 13501

Date Received 10/04/14 **AmeriSci Job #** 214101690
Date Examined 10/07/14 **P.O. #**
ELAP # 11480 **Page** 1 **of** 8
RE: 14215; G&H Demolition, Paragon Indiana; Former Dunlap
Tire, 2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01 1 Location: 10th Floor - Window Glazing Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 1.2 %	214101690-01	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
02 1 Location: 10th Floor - Window Glazing Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 5.1 %	214101690-02	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
03 2 Location: 10th Floor - Stackdoor Packing (AHU) Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 50 %, Non-fibrous 50 %	214101690-03	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
04 2 Location: 10th Floor - Stackdoor Packing (AHU) Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 50 %, Non-fibrous 50 %	214101690-04	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
05 3 Location: 10th Floor - Stackdoor Gasket (AHU) Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 35 %, Non-fibrous 2.4 %	214101690-05	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report

14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
06 3	214101690-06 Location: 10th Floor - Stackdoor Gasket (AHU)	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 50 %, Non-fibrous 5.4 %			
07 4	214101690-07 Location: 10th Floor - Blown In Insulation	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 95 %, Non-fibrous 5 %			
08 4	214101690-08 Location: 10th Floor - Blown In Insulation	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 95 %, Non-fibrous 5 %			
09 5	214101690-09 Location: 10th Floor - Window Caulk	Yes	2.8 % (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Chrysotile 2.8 % Other Material: Non-fibrous 10.5 %			
10 5	214101690-10 Location: 10th Floor - Window Caulk		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
11 6	214101690-11 Location: 10th Floor - Lg. Breeching Elbow	Yes	5.3 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 5.3 % Other Material: Fibrous glass 15 %, Non-fibrous 79.7 %			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report

14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
12 6	214101690-12 Location: 10th Floor - Lg. Breeching Elbow		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
13 6	214101690-13 Location: 10th Floor - Lg. Breeching Elbow		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
14 7	214101690-14 Location: 9th Floor - Cooling Tower Main Insulation	Yes	6.8 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 6.8 % Other Material: Fibrous glass 50 %, Non-fibrous 43.2 %			
17 8	214101690-15 Location: 9th Floor - Cooling Tower Patch Material	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: OffWhite/Black, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 65 %, Non-fibrous 35 %			
19 9	214101690-16 Location: 9th Floor - AHU Door Packing	Yes	2.5 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Brown, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 2.5 % Other Material: Fibrous glass 90 %, Non-fibrous 7.5 %			
20 9	214101690-17 Location: 9th Floor - AHU Door Packing		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
21 10	214101690-18 Location: 9th Floor - 18" Breeching Jacket	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Silver/Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 30 %, Non-fibrous 23.2 %			
22 10	214101690-19 Location: 9th Floor - 18" Breeching Jacket	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Silver/Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 8 %, Non-fibrous 2 %			
23 11	214101690-20 Location: 9th Floor - Mudded Pipe Fitting	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 65 %, Non-fibrous 35 %			
25 11	214101690-21 Location: 8th Floor - Mudded Pipe Fitting	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 65 %, Non-fibrous 35 %			
26 8	214101690-22 Location: 8th Floor - Cooling Tower Patch Material	Yes	8.5 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 8.5 % Other Material: Fibrous glass 65 %, Non-fibrous 26.5 %			
29 7	214101690-23 Location: 9th Floor - Cooling Tower Main Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report

14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
32 12	214101690-24 Location: 8th Floor - Fiberglass Pipe Jacket Mastic	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Silver/Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 7 %, Non-fibrous 1.3 %			
33 12	214101690-25 Location: 8th Floor - Fiberglass Pipe Jacket Mastic	No	NAD (by NYS ELAP 198.6) by David W. Roderick on 10/07/14
Analyst Description: Silver/Yellow, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 5 %, Non-fibrous 1.8 %			
34 8	214101690-26 Location: 6th Floor - Cooling Tower Patch Material		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
37 7	214101690-27 Location: 5th Floor - Cooling Tower Main Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
41 13	214101690-28 Location: 5th Floor - Canvas Covered Duct Insulation	Yes	6.8 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 6.8 % Other Material: Fibrous glass 50 %, Non-fibrous 43.2 %			
42 13	214101690-29 Location: 5th Floor - Canvas Covered Duct Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report

14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
43 13	214101690-30 Location: 5th Floor - Canvas Covered Duct Insulation		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
44 14	214101690-31 Location: 5th Floor - AHU Door Gasket	Yes	80 % (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: OffWhite, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 80.0 % Other Material: Non-fibrous 20 %			
45 14	214101690-32 Location: 5th Floor - AHU Door Gasket		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
46 15	214101690-33 Location: 5th Floor - Interior Packing AHU	Yes	9.5 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 9.5 % Other Material: Fibrous glass 50 %, Non-fibrous 40.5 %			
47 15	214101690-34 Location: 5th Floor - Interior Packing AHU		NA/PS
Analyst Description: Bulk Material Asbestos Types: Other Material:			
48 11	214101690-35 Location: 1st Floor - Mudded Pipe Fitting	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Grey, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Fibrous glass 40 %, Non-fibrous 60 %			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
49 16	214101690-36 Location: 3rd Floor - Gypsum Joint Compound	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: OffWhite, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
50 16	214101690-37 Location: 3rd Floor - Gypsum Joint Compound	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: OffWhite, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
51 17A	214101690-38 Location: 3rd Floor - Gypsum Wall 1/2"	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Brown/Grey, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 %			
52 17B	214101690-39 Location: 3rd Floor - Gypsum Wall 5/8"	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: Brown/Grey, Heterogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Cellulose 15 %, Non-fibrous 85 %			
53 18	214101690-40 Location: 1st Floor - Pipe Insulation	No	NAD (by NYS ELAP 198.1) by David W. Roderick on 10/07/14
Analyst Description: White, Homogeneous, Fibrous, Bulk Material Asbestos Types: Other Material: Synthetic fibers 10 %, Non-fibrous 90 %			
54 18	214101690-41 Location: 1st Floor - Pipe Insulation	Yes	5.8 % (EPA 400 PC) by David W. Roderick on 10/07/14
Analyst Description: White, Homogeneous, Fibrous, Bulk Material Asbestos Types: Chrysotile 5.8 % Other Material: Non-fibrous 94.2 %			

Client Name: Eisenbach & Ruhnke Engineering, P.C.

PLM Bulk Asbestos Report

14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire,
2214 Whitesboro St., Utica

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
55 18	214101690-42 Location: 1st Floor - Pipe Insulation		NA/PS

Analyst Description: Bulk Material

Asbestos Types:

Other Material:

Reporting Notes:

Analyzed by: David W. Roderick

*NAD/NSD =no asbestos detected; NA =not analyzed; NA/PS=not analyzed/positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 200546-0), ELAP PLM Method 198.1 for NY friable samples, which includes the identification and quantitation of vermiculite or 198.6 for NOB samples or EPA 400 pt ct by EPA 600/M4-82-020 (NY ELAP Lab ID11480); Note:PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non asbestos-containing in NY State (also see EPA Advisory for floor tile, FR 59,146,38970,8/1/94) National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the lab.This PLM report relates ONLY to the items tested. AIHA Lab # 102843, RI Cert#AAL-094, CT Cert#PH-0186, Mass Cert#AA000054.

Reviewed By:

END OF REPORT

Client Name: Eisenbach & Ruhnke Engineering, P.C.

Table I
Summary of Bulk Asbestos Analysis Results
 14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire, 2214 Whitesboro St., Utica

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	01	1	0.430	1.9	97.0	1.0	NAD	Chrysotile <1.0
Location: 10th Floor - Window Glazing								
02	02	1	0.276	14.5	80.4	5.1	NAD	NAD
Location: 10th Floor - Window Glazing								
03	03	2	---	---	---	---	NAD	NA
Location: 10th Floor - Stackdoor Packing (AHU)								
04	04	2	---	---	---	---	NAD	NA
Location: 10th Floor - Stackdoor Packing (AHU)								
05	05	3	0.270	61.9	0.7	37.4	NAD	NAD
Location: 10th Floor - Stackdoor Gasket (AHU)								
06	06	3	0.397	42.3	2.3	55.4	NAD	NAD
Location: 10th Floor - Stackdoor Gasket (AHU)								
07	07	4	---	---	---	---	NAD	NA
Location: 10th Floor - Blown In Insulation								
08	08	4	---	---	---	---	NAD	NA
Location: 10th Floor - Blown In Insulation								
09	09	5	0.180	30.6	56.1	10.5	Chrysotile 2.8	NA
Location: 10th Floor - Window Caulk								
10	10	5	0.194	33.0	56.2	10.8	NA/PS	NA
Location: 10th Floor - Window Caulk								
11	11	6	---	---	---	---	Chrysotile 5.3	NA
Location: 10th Floor - Lg. Breeching Elbow								
12	12	6	---	---	---	---	NA/PS	NA
Location: 10th Floor - Lg. Breeching Elbow								
13	13	6	---	---	---	---	NA/PS	NA
Location: 10th Floor - Lg. Breeching Elbow								
14	14	7	---	---	---	---	Chrysotile 6.8	NA
Location: 9th Floor - Cooling Tower Main Insulation								
15	17	8	---	---	---	---	NAD	NA
Location: 9th Floor - Cooling Tower Patch Material								
16	19	9	---	---	---	---	Chrysotile 2.5	NA
Location: 9th Floor - AHU Door Packing								

Client Name: Eisenbach & Ruhnke Engineering, P.C.

Table I
Summary of Bulk Asbestos Analysis Results
 14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire, 2214 Whitesboro St., Utica

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	20	9	---	---	---	---	NA/PS	NA
Location: 9th Floor - AHU Door Packing								
18	21	10	0.154	44.8	1.9	53.2	NAD	NAD
Location: 9th Floor - 18" Breeching Jacket								
19	22	10	0.259	86.1	3.9	10.0	NAD	NAD
Location: 9th Floor - 18" Breeching Jacket								
20	23	11	---	---	---	---	NAD	NA
Location: 9th Floor - Mudded Pipe Fitting								
21	25	11	---	---	---	---	NAD	NA
Location: 8th Floor - Mudded Pipe Fitting								
22	26	8	---	---	---	---	Chrysotile 8.5	NA
Location: 8th Floor - Cooling Tower Patch Material								
23	29	7	---	---	---	---	NA/PS	NA
Location: 9th Floor - Cooling Tower Main Insulation								
24	32	12	0.205	78.5	13.2	8.3	NAD	NAD
Location: 8th Floor - Fiberglass Pipe Jacket Mastic								
25	33	12	0.118	89.0	4.2	6.8	NAD	NAD
Location: 8th Floor - Fiberglass Pipe Jacket Mastic								
26	34	8	---	---	---	---	NA/PS	NA
Location: 6th Floor - Cooling Tower Patch Material								
27	37	7	---	---	---	---	NA/PS	NA
Location: 5th Floor - Cooling Tower Main Insulation								
28	41	13	---	---	---	---	Chrysotile 6.8	NA
Location: 5th Floor - Canvas Covered Duct Insulation								
29	42	13	---	---	---	---	NA/PS	NA
Location: 5th Floor - Canvas Covered Duct Insulation								
30	43	13	---	---	---	---	NA/PS	NA
Location: 5th Floor - Canvas Covered Duct Insulation								
31	44	14	---	---	---	---	Chrysotile 80.0	NA
Location: 5th Floor - AHU Door Gasket								
32	45	14	---	---	---	---	NA/PS	NA
Location: 5th Floor - AHU Door Gasket								

Client Name: Eisenbach & Ruhnke Engineering, P.C.

Table I
Summary of Bulk Asbestos Analysis Results
 14215; G&H Demolition, Paragon Indiana; Former Dunlap Tire, 2214 Whitesboro St., Utica

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
33	46	15	---	---	---	---	Chrysotile 9.5	NA
Location: 5th Floor - Interior Packing AHU								
34	47	15	---	---	---	---	NA/PS	NA
Location: 5th Floor - Interior Packing AHU								
35	48	11	---	---	---	---	NAD	NA
Location: 1st Floor - Mudded Pipe Fitting								
36	49	16	---	---	---	---	NAD	NA
Location: 3rd Floor - Gypsum Joint Compound								
37	50	16	---	---	---	---	NAD	NA
Location: 3rd Floor - Gypsum Joint Compound								
38	51	17A	---	---	---	---	NAD	NA
Location: 3rd Floor - Gypsum Wall 1/2"								
39	52	17B	---	---	---	---	NAD	NA
Location: 3rd Floor - Gypsum Wall 5/8"								
40	53	18	---	---	---	---	NAD	NA
Location: 1st Floor - Pipe Insulation								
41	54	18	---	---	---	---	Chrysotile 5.8	NA
Location: 1st Floor - Pipe Insulation								
42	55	18	---	---	---	---	NA/PS	NA
Location: 1st Floor - Pipe Insulation								

Analyzed by: Madell E. Collins  Date Analyzed 10/7/2014

**Quantitative Analysis (Semi/Full); Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR or ELAP 198.1 for New York friable samples or ELAP 198.6 for New York NOB samples; TEM (Semi/Full) by EPA 600/R-93/116 (not covered by NVLAP Bulk accreditation) or ELAP 198.4; for New York samples; NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantitation for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab # 102843, NVLAP Lab Code 200546-0, NYSDOH ELAP Lab ID#11480.

Warning Note: PLM limitation: only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogenous materials).

Reviewed By: 

**EISENBACH & RUHNKE ENGINEERING, P.C.**291 GENESEE STREET, UTICA, NEW YORK 13501
315-735-1916 • FAX 315-735-6365 • E-MAIL info@ereng.com**BULK SAMPLE LOG****ASBESTOS**Log No: 1 of 3

CLIENT: <u>G & H Demolition, PARAGON INDUSTRIAL</u>		ANALYSIS: <input type="checkbox"/> PLM Only <input type="checkbox"/> TEM Only <input checked="" type="checkbox"/> PLM/TEM as required by ELAP <input type="checkbox"/> Other _____
PROJECT NAME/LOCATION: <u>Former Dunlap Tire, 2214 Whitesboro St, UTICA</u>		
SAMPLES COLLECTED BY: <u>Eric Dousharm</u>		
NYS DEPT OF LABOR CERTIFICATE NO. <u>93-10480</u>		TURNAROUND TIME: <input type="checkbox"/> RUSH <input type="checkbox"/> 12 Hour <input type="checkbox"/> 24 HOUR <input type="checkbox"/> 48 Hour <input checked="" type="checkbox"/> 72 Hour <input type="checkbox"/> Other _____
DATE SAMPLED: <u>9-12-14</u>	PROJECT#: <u>14215</u>	

NOTES:

Held until 9-29-14214101690

SAMPLE NUMBER	HOMO ID #	MATERIAL SAMPLED	LOCATION	ANALYZE ONLY IF SAMPLE TO THE LEFT IS NEGATIVE BY PLM/TEM
-01	1	Window GLAZING	10 th Floor	-02
-02	1	Window GLAZING	" "	
-03	2	Stack door Packing (AHU)	" "	-04
-04	2	Stack door Packing (AHU)	" "	
-05	3	Stack door Gasket (AHU)	" "	-06
-06	3	Stack door Gasket (AHU)	" "	
-07	4	Blown in insulation	" "	-08
-08	4	Blown in insulation	" "	
-09	5	Window CAULK	" "	-10
-10	5	Window CAULK	" "	
-11	6	Lg Breeching elbow	" "	-12
-12	6	Lg Breeching elbow	" "	-13
-13	6	Lg Breeching elbow	" "	
-14	7	Cooling tower MAIN insulation	9 th Floor	-29
-15	-	NOT USED		
-16	-	NOT USED		
-17	8	Cooling tower patch material		-26
-18	-	NOT USED		

	PRINTED NAME	SIGNATURE	COMPANY	DATE	# OF SAMPLES
Remitted by:	<u>Eric Dousharm</u>	<u>[Signature]</u>	<u>ER</u>	<u>10/2/14</u>	<u>15</u>
Received by:	<u>Rodisha Samuel</u>	<u>[Signature]</u>		<u>10/4/14</u> <u>15:40</u>	
PLEASE EMAIL RESULTS TO <u>edousharm@erengpc.com</u> ATTN:					
PLEASE FAX RESULTS TO () - ATTN:					



EISENBACH & RUHNKE ENGINEERING, P.C.
291 GENESEE STREET, UTICA, NEW YORK 13501
315-735-1916 • FAX 315-735-6365 • E-MAIL info@ereng.com

BULK SAMPLE LOG

ASBESTOS

Log No: 2 of 3

CLIENT: <u>G & H Demolition, PARAGON INDUSTRIAL</u>		ANALYSIS: <input type="checkbox"/> PLM Only <input type="checkbox"/> TEM Only <input checked="" type="checkbox"/> PLM/TEM as required by ELAP <input type="checkbox"/> Other _____
PROJECT NAME/LOCATION: <u>Former Dunlap Tire, 2214 Whiteshore St, Utica</u>		
SAMPLES COLLECTED BY: <u>Eric Dousharm</u>		
NYS DEPT OF LABOR CERTIFICATE NO. <u>93-10480</u>		TURNAROUND TIME: <input type="checkbox"/> RUSH <input type="checkbox"/> 12 Hour <input type="checkbox"/> 24 HOUR <input type="checkbox"/> 48 Hour <input checked="" type="checkbox"/> 72 Hour <u>214101690</u>
DATE SAMPLED: <u>9-12-14</u>	PROJECT#: <u>14215</u>	

NOTES:

SAMPLE NUMBER	HOMO ID #	MATERIAL SAMPLED	LOCATION	ANALYZE ONLY IF SAMPLE TO THE LEFT IS NEGATIVE BY PLM/TEM
-19	9	AHU door packing	9 th Floor	-20
-20	9	AHU door packing	" "	
-21	10	18" Breaching Jacket	" "	-22
-22	10	18" Breaching Jacket	" "	
-23	11	mudded Pipe Fitting	" "	-25
-24	-	NOT Used		
-25	11	mudded Pipe Fitting	8 th Floor	-48
-26	8	cooling tower patch material	" "	-34
-27	-	NOT Used		
-28	-	NOT Used		
-29	7	cooling tower main insulation	8 th Floor	-37
-30	-	NOT Used		
-31	-	NOT Used		
-32	12	Fiberglass Pipe Jacket mastic	8 th Floor	-33
-33	12	Fiberglass Pipe Jacket mastic	" "	
-34	8	cooling tower patch material	6 th Floor	
-35	-	NOT Used		
-36	-	NOT Used		

	PRINTED NAME	SIGNATURE	COMPANY	DATE	# OF SAMPLES
Remitted by:	<u>Eric Dousharm</u>	<u>E. Dousharm</u>	<u>E & R</u>	<u>10/2/14</u>	<u>11</u>
Received by:	<u>Kadesha Samel</u>	<u>Samel</u>		<u>10/4/14</u>	
PLEASE EMAIL RESULTS TO <u>edousharm@ereng.com</u> ATTN:					
PLEASE FAX RESULTS TO () ATTN:					



EISENBACH & RUHNKE ENGINEERING, P.C.
291 GENESEE STREET, UTICA, NEW YORK 13501
315-735-1916 · FAX 315-735-6365 · E-MAIL info@erengc.com

BULK SAMPLE LOG
ASBESTOS

Log No: 3 of 3

CLIENT: <u>G & H Demolition, Paragon Indiana</u>		ANALYSIS: <input type="checkbox"/> PLM Only <input type="checkbox"/> TEM Only <input checked="" type="checkbox"/> PLM/TEM as required by ELAP <input type="checkbox"/> Other _____
PROJECT NAME/LOCATION: <u>Former Dunlap tire, 2214 Whitehorn St, Utica</u>		
SAMPLES COLLECTED BY: <u>Eric Dougharn</u>		
NYS DEPT OF LABOR CERTIFICATE NO. <u>93-10480</u>		TURNAROUND TIME: <input type="checkbox"/> RUSH <input type="checkbox"/> 12 Hour <input type="checkbox"/> 24 HOUR <input type="checkbox"/> 48 Hour <input checked="" type="checkbox"/> 72 Hour <input type="checkbox"/> Other _____
DATE SAMPLED: <u>9-12-14</u>	PROJECT#: <u>14215</u>	214101690
NOTES:		

SAMPLE NUMBER	HOMO ID #	MATERIAL SAMPLED	LOCATION	ANALYZE ONLY IF SAMPLE TO THE LEFT IS NEGATIVE BY PLM/TEM
-37	7	cooling tower MAIN insulation	5 th Floor	
-38	-	NOT Used		
-39	-	NOT Used		
-40	-	NOT Used		
-41	13	CANVAS covered duct insulation	5 th Floor	-42
-42	13	CANVAS covered duct insulation	" "	-43
-43	13	CANVAS covered duct insulation	" "	
-44	14	AHU door Gasket	" "	-45
-45	14	AHU door Gasket	" "	
-46	15	Interior Packing AHU	" "	-47
-47	15	Interior Packing AHU	" "	
-48	11	mudded Pipe Fitting	1 st Floor	
-49	16	Gypsum Joint Compound	3 rd Floor	50
-50	16	Gypsum Joint Compound	" "	
-51	17A	Gypsum wall 1/2"	" "	
-52	17B	Gypsum wall 5/8"	" "	
-53	18	Pipe insulation	1 st Floor	-54
-54	18	Pipe insulation	" "	-55
-55	18	Pipe insulation	" "	

	PRINTED NAME	SIGNATURE	COMPANY	DATE	# OF SAMPLES
Remitted by:	<u>Eric Dougharn</u>	<u>[Signature]</u>	<u>E & R</u>	<u>10/2/14</u>	<u>18</u>
Received by:	<u>Kadesha Samvet</u>	<u>[Signature]</u>		<u>10/4/14</u>	
PLEASE EMAIL RESULTS TO <u>edougharn@erengc.com</u> ATTN:					
PLEASE FAX RESULTS TO () ATTN:					